BLUETOOTH® TELEPHONE COMPATIBILITY

Model Selected: Continental GT 2007

BENTLEY

Blackberry 8100					Not Recommended
Software Version: 4.2.051					Profile: HFP

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✖	Not Supported	✖	✖	Not Supported

Blackberry 8700g					Not Recommended
Software Version: 4.1.0.351					Profile: HFP

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✖	Not Supported	✖	✖	Not Supported

Blackberry 8800					Not Recommended
Software Version: 4.2.1.72					Profile: HFP

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✖	Not Supported	✖	✖	Not Supported

Blackberry Pearl					Not Recommended
Software Version: N/A					Profile: HFP

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✖	Not Supported	✖	✖	Not Supported

LG KE850 Prada					Not Recommended
Software Version: KE850P40-EUR-v10n					Profile: HFP

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✖	Not Supported	✖	✖	Not Supported

Motorola KRZR K1					Not Recommended
Software Version: R4527_G_08.22.07R					Profile: HFP

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✖	✖	✖	✖	✖

Motorola RIZR Z3					Not Recommended
Software Version: R452B_G_08.01.02R					Profile: HFP

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✖	✖	✖	✖	✖

Motorola SLVR Software Version: FLEX: SE5135AXXF1078 SW: R376_G_0E.65.25R				**Not Recommended** Profile: HFP	
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✘	✘	✘	✘	✘

Motorola V3x Software Version: R252211LD_U_85.97.41P				**Fully Compatible** Profile: HFP	
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✔	Not Supported	✘	✘	Not Supported

Motorola V551 Software Version: R472_G_08.18.16R_0A				**Fully Compatible** Profile: HFP	
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✔	Not Supported	✘	✘	Not Supported

Nokia 3250 Software Version: 3.23 RM-38 15-05-06				**Fully Compatible** Profile: rSAP	
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✔	✔	✔	Not Supported	✔

Nokia 6021 Software Version: 4.5				**Fully Compatible** Profile: rSAP	
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✔	✔	✔	Not Supported	✔

Nokia 6280 Software Version: 3.6				**Fully Compatible** Profile: rSAP	
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✔	✔	✔	Not Supported	✔

Nokia E50 Software Version: 7.13				**Fully Compatible** Profile: rSAP	
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✔	✔	✔	Not Supported	✔

Nokia E60 Software Version: 2.0618.06.05				**Fully Compatible** Profile: rSAP	
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✔	✔	✔	Not Supported	✔

| **Nokia E65** | | | | | **Fully Compatible** |
Software Version: 1.0633.18.01					Profile: rSAP
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✓	✓	✓	Not Supported	✓

| **Nokia N71** | | | | | **Fully Compatible** |
Software Version: v2.0613.1.12.1 RM-67					Profile: rSAP
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✓	✓	✓	Not Supported	✓

| **Nokia N80** | | | | | **Fully Compatible** |
Software Version: v4.0632.0.38					Profile: rSAP
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✓	✓	✓	Not Supported	✓

| **Samsung D900** | | | | | **Fully Compatible** |
Software Version: X820NXXFJ1					Profile: HFP
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✓	Not Supported	✗	✗	Not Supported

| **Samsung SGH-D840** | | | | | **Fully Compatible** |
Software Version: D840SSFL1					Profile: HFP
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✓	Not Supported	✗	✗	Not Supported

| **Samsung U100** | | | | | **Fully Compatible** |
Software Version: D840SSFL1					Profile: HFP
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✓	Not Supported	✗	✗	Not Supported

| **Sony Ericsson K800i** | | | | | **Fully Compatible** |
Software Version: R1ED001					Profile: HFP
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✓	Not Supported	✗	✗	Not Supported

| **Sony Ericsson M600i** | | | | | **Partial Function** |
Software Version: CXC162071 R6A16					Profile: HFP
	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✓	Not Supported	✗	✗	Not Supported

Sony Ericsson P990i — Fully Compatible
Software Version: R1JG001 **Profile: HFP**

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✓	Not Supported	✗	✗	Not Supported

Sony Ericsson W800i — Not Recommended
Software Version: R1JG001 **Profile: HFP**

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✗	✗	✗	✓	✓

Sony Ericsson W950i — Not Recommended
Software Version: "CXC162037 R9EC001" **Profile: HFP**

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✗	✗	✗	✗	✗

Sony Ericsson Z520i — Not Recommended
Software Version: R1JG001 **Profile: HFP**

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✗	✗	✗	✓	✓

Toshiba Portege — Not Recommended
Software Version: 02.17BAI **Profile: HFP**

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✗	Not Supported	✗	✗	Not Supported

Vertu Ascent — Fully Compatible
Software Version: 07_w06 **Profile: rSAP**

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✓	✓	✓	Not Supported	✓

Vertu Constellation — Fully Compatible
Software Version: 501.01 **Profile: rSAP**

	Hands-Free Call	Phonebook Use	Auto-Connection	Conference Call	Network Info
	✓	✓	✓	Not Supported	✓